ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura
Street ID	**Street Name**	**Significant Landmark**
W0132, W0157, W0151, W0149, W0161, W0300, W0155, W	NA, 4th Crs Lakshmi Sagar Lyt	Doddamma Temple
Segment No.	**Total Length (m)**	
7/C-W0132/S051936	673.36	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	164.40	77.599898	13.071542	77.599555	13.070095	Ayappa temple road	Dead End
2	123.88	77.600204	13.071480	77.599952	13.070388	Ayappa temple road	Dead End
3	116.73	77.600526	13.071417	77.600290	13.070388	Ayappa temple road	Dead End
4	128.08	77.600821	13.071339	77.600558	13.070210	Ayappa temple road	Dead End
5	140.27	77.601132	13.071286	77.600832	13.070053	Ayappa temple road	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to drains of 11th to 14th Cross Roads of Jakkur Layout in ward no 07, Byatarayanapura, Kodigehalli Sub Division	5000000	2017-18
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	1.Construction of RCC Drain.2.Providing and laying Rcc Covering slabs.	007-18-000007
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/85/17-18	02/03/2018	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
20/06/2018	19/06/2020	Yes

Contractor Details

e of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
s Executive Engineer, (.R.I.D.L		0.00
Phone No.	**E-Mail ID**	
9480826123		

Field Inspection Details

Number of Trees	Any Other Information	Name
4		Pushpalatha.N.D
Date of Inspection	**Remarks**	
05/07/2018		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0132, W0157, W0151, W0149,

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	R.L.Parameshwaraiah	11/07/2018	06/08/2018	As proposed
SE	Vasu K M	07/07/2018	06/08/2018	Completed
EE	Mohandas H.T	06/07/2018	20/07/2018	verified
AEE	Ranganath	06/07/2018	20/07/2018	verified
AE	Pushpalatha.N.D	06/07/2018	20/07/2018	Mobile Verification Done
AE	Pushpalatha.N.D	20/06/2018	20/07/2018	Forwarded

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0132, W0157, W0151, W0149, W0161, W

Pushpalatha.N.D
AE(W7)

Assistant Executive Engineer,
Kodigehalli Sub Division,
Yelahanka Zone, B.B.M.P.,
Bangalore.